

Excess Justification Report

For Excess Lot

FY16-020

Item #	Part #	Serial #	Description	Cond	Qty	Remarks
0001	AA34-300	102761	Universal Radio Interface Audio Amplifier, Cond. 7	7	1	Removed from a Cessna 206 on 10/8/15. Deinstall, recertification required. Mfg. Wulfsberg
0002	S3317-3	1168	Indicator, Fuel Quantity, Cond. 7	7	1	Removed from a Cessna 206 on 10/13/15. Deinstall, recertification required. Mfg. Rochester Gauges
0003	066-1055-71	85979	Audio/ Intercom Panel, KMA-24H-71, Cond. 7	7	1	Removed from a Cessna 206 on 10/17/15, Inop. Mfg. Bendix King
0004	069-01034-0102	21308	Receiver, KLN-94, Cond. 7	7	1	Removed from a Cessna 206 on 10/13/15. Deinstall, recertification required. Mfg. Honeywell
0005	066-1062-00	37384	Transponder Kt76a, Cond. 7	7	1	Repair tag dated 1/3/91, no company name on tag, recertify. Mfg. King Radio Corp.
0006	066-01156-0101	8257	Transponder, KT76C, Cond. 7	7	1	Removed from an AS350 Airbus helicopter on 12/7/15. Upgrade removed in working condition. Mfg. Bendix King
0007	504-0017-908	2062	Indicator, Attitude Gyro, Cond. 7	7	1	Removed from an MD369 on 6/7/15, condition unknown. Mfg. Aviation Instruments
0008	655234A13	NSN	Tuned Nozzle Assembly, Continental. Cond. 7	7	1	Removed from a Continental engine on 2/1/16. Set of 6 nozzles internally scored. Suspect fuel spray pattern is incorrect.
0009	100-364295-3	796-BW-90-L6812	Control, Windshield, Temperature, Cond. 7	7	1	Removed from a Beech King Air on 1/16/16, broken screw. Mfg. Beech
0010	130-364090-5	03101105ICT	Module Circuit Board Assembly, Air Conditioner, Cond. 7	7	1	Removed from a King Air on 6/5/15, circuit board card will not allow heat in auto mode. Mfg. Hawker Beechcraft.
0011	46150	247315	Egt Gauge, Cond. 7	7	1	Removed on 2/22/16, deinstall, condition unknown. Mfg. Alcor
0012	C662037-0103	143280AM	Fuel Flow Indicator, Cond. 7	7	1	Removed from a Cessna 206 on 2/22/16, deinstall, condition unknown. Mfg. United Instruments
0013	066-1055-71	85392	Audio/ Intercom Panel, KMA-24H-71, Cond. 7	7	1	Removed from a Cessna 206 on 3/2/16, intermittent audio. Mfg. Bendix King
0014	1394T100-7Z	9412-59	Turn Coordinator, Cond. 7	7	1	Removed from a Cessna 210 on 11/27/15, inop. Mfg. Electric Gyro Group
0015	0100-002	0403K045	Display Mount, Cond. 7	7	1	Removed from a Cessna Citation on 3/30/16. Installed new audio system. Mfg. Rosen Aviation Displays LLC.
0016	N2412-12	204020638	Power Supply, Cond. 7	7	1	Removed from a Cessna Citation on 3/30/16. Installed a new audio system. Mfg. Astron Corp.
0017	97-10229-001	1375	Remote Switch, Cond. 7	7	1	Removed from a Cessna Citation on 3/30/16. Installed new audio system. Mfg. MSI Avionics
0018	247	1477	Audio Mixing Amplifier, Cond. 7	7	1	Removed from a Cessna Citation on 3/30/16. Installed new audio system. Mfg. Northern Airborne Tech.
0019	5636-1	504	Audio Control Panel, Cond. 7	7	1	Removed from a Cessna Citation on 3/30/16. Installed new audio system. Mfg. AVTech
0020	5636-1	910	Audio Control Panel, Cond. 7	7	1	Removed from a Cessna Citation on 3/30/16. Installed new audio system. Mfg. AVTech
0021	C290D4K/T4	850952	Governor Assembly, Propeller, Cond. 7	7	1	Removed from a Cessna 206 on 5/12/15, worn component, needs overhaul. Mfg. McCauley
0022	C290D4K/T4	800977	Governor Assembly, Propeller, Cond. 7	7	1	Rejected for install on a Cessna 206, due to lack of total time on the 8130. Total time unknown, needs overhaul and recertification. Mfg. McCauley
0023	C290D4K/T4	741127	Governor Assembly, Propeller, Cond. 7	7	1	Removed from a Cessna 206 on 5/27/14. Serviced but no time on 8130, needs overhaul and recertification. Mfg. McCauley
0024	E23062753	TM47-815	#1 Turbine Nozzle, Cond. 7	7	1	Removed from a Rolls Royce Engine on 2/4/14. Overhaul and recertify. Mfg. Rolls Royce
0025	066-1072-00	40422	Receiver, ADF, KR-87, Cond. 7	7	1	Removed from a Cessna 206 on 6/12/15. Digital display garbled and/or digits missing when unit heats up. Some of the sections do not work. Mfg. Bendix King

Excess Justification Report

For Excess Lot

FY16-020

Item #	Part #	Serial #	Description	Cond	Qty	Remarks
0026	066-1072-00	45368	Receiver, ADF, KR-87, Cond. 7	7	1	Removed from a Cessna on 12/17/14. Intermittent, unable to receive, internal condition unknown. Full function check due. Mfg. Bendix King
0027	066-1055-71	82300	Audio/ Intercom Panel, KMA-24H-71, Cond. 7	7	1	Removed from a Cessna 206 on 5/11/15. Sidetone needs adjusting. Mfg. Bendix King
0028	066-1055-71	164883	Audio/ Intercom Panel, KMA-24H-71, Cond. 7	7	1	Removed from a Cessna 206 on 5/5/15. Weak sidetone, can not hear pilot. Mfg. Bendix King
0029	066-1055-71	164022	Audio/ Intercom Panel, KMA-24H-71, Cond. 7	7	1	Removed from a Cessna 206 on 2/24/15. Pox's intercom inop. Mfg. Bendix King
0030	066-1055-71	164858	Audio/ Intercom Panel, KMA-24H-71, Cond. 7	7	1	Removed from a Cessna 206 on 4/28/15, inop. Mfg. Bendix King
0031	066-1055-71	164836	Audio/ Intercom Panel, KMA-24H-71, Cond. 7	7	1	Removed from a Cessna 206 on 5/4/15, inop. Mfg. Bendix King
0032	066-3038-00	9673	Indicator, Rmi, KI-229, Cond. 7	7	1	Removed from an Airbus 350 on 12/7/15. removed in known working condition. Mfg. Bendix King
0033	101-364582-1	980-A91	PC Board, LT Test & Hyd Gear Time Delay, Cond. 7	7	1	Removed from a King Air B300C on 4/23/15. Left igh. on, engine anti ice & fuel cross feed working intermittent. Mfg. Beechcraft
0034	101-381015-3	1397	Valve Assembly, Bleed Air Shut Off, Cond. 7	7	1	Removed from a King Air 350 on 4/29/15. Valve sticks in open position. Mfg. ASC
0035	066-1055-71	164868	Audio/ Intercom Panel, KMA-24H-71, Cond. 7	7	1	Removed from a Cessna on 4/13/15. No ics audio control. Mfg. Bendix King
0036	066-1055-71	162091	Audio/ Intercom Panel, KMA-24H-71, Cond. 7	7	1	Removed from a Cessna on 6/5/15. ICS side tones intermittent. Mfg. Bendix King
0037	066-1055-71	85947	Audio/ Intercom Panel, KMA-24H-71, Cond. 7	7	1	Removed from an MD500 on 8/4/15. Comm 2 inop/mounting screw stripped. Mfg. Bendix King
0038	069-1025-27	50194	Transceiver, NAV Comm, KX-165, Cond. 7	7	1	Removed from a Cessna 206 on 9/14/12. Transmission unreadable by ATC and transmit "T" light flickers. Both are intermittent. Mfg. Bendix King
0039	069-1025-27	12738	Transceiver, NAV Comm, KX-165, Cond. 7	7	1	Removed from a MD369 on 4/29/15. Weak transmit, will not transmit sometimes. Mfg. King Radio
0040	069-1025-27	48501	Transceiver, NAV Comm, KX-165, Cond. 7	7	1	Removed from a MD369 on 4/22/15. No squelch disable. Some frequencies are difficult to transmit and receive on. Mfg. Bendix King
0041	069-1025-27	2975	Transceiver, NAV Comm, KX-165, Cond. 7	7	1	Removed from a Cessna 206 on 7/30/15, inop. Mfg. King Radio
0042	069-1025-27	50186	Transceiver, NAV Comm, KX-165, Cond. 7	7	1	Removed from a Cessna 206 on 2/24/11. ILS & VOR inop. Mfg. Bendix King
0043	069-1025-25	63528	Transceiver, Nav Comm, KX-165, Cond. 7	7	1	Removed from an Airbus 350 on 12/8/15. Upgrade required, in working condition. Mfg. Bendix King
0044	069-1025-25	64687	Transceiver, Nav Comm, KX-165, Cond. 7	7	1	Removed from an MD500 on 8/3/15. Numerous nav-unsure. Replaces HSI also. Mfg. Bendix King
0045	066-1068-00	11961	Dme, Kn62a, Cond. 7	7	1	Removed from an MD369D on 6/27/13. Display washed out. Mfg. King Radio
0046	066-1068-00	11934	Dme, Kn62a, Cond. 7	7	1	Removed from an MD369D on 6/19/13, Front bezal id. letters unreadable above sel. sw. Mfg. King Radio
0047	48B22314	CGN3960	Controller Sloped, Cond. 7	7	1	Core removed from a Lycoming engine on 6/15/11. Total time 1988. Requires overhaul. Mfg. Rayjay Consolidated Fuel Systems.
0048	48B22314	JLN00514	Controller Sloped, Cond. 7	7	1	Removed from a Lycoming engine on 8/3/12. TBO, required overhaul. Mfg. Rayjay Consolidated Fuel Systems
0049	48B22314	CBN1569	Controller Sloped, Cond. 7	7	1	Removed from a Lycoming engine on 10/6/11. Requires overhaul. Mfg. Rayjay Consolidated Fuel Systems
0050	481058-9005	DC07747	Controller, Cond. 7	7	1	Removed from a Lycoming engine on 7/29/10. Requires overhaul. Mfg. Rayjay Consolidated Fuel Systems

Excess Justification Report

For Excess Lot

FY16-020

Item #	Part #	Serial #	Description	Cond	Qty	Remarks
0051	48B22314-85	MAO00154	Controller, Cond. 7	7	1	Removed from a Lycoming engine on 3/15/13, condition unknown. Mfg. Kelly Aerospace
0052	632774-2A14	NSN	Throttle and Control Assy. Cond. 7	7	2	Removed from a Continental engine on 12/12/15. Engine TBO, condition unknown. Mfg. TCM
0053	2C27-3	7AW724	Cartridge, Fuel Boost Pump, Cond. 7	7	1	Removed from a Eurocopter MBB on 10/8/09. Low pressure, requires repair/overhaul. Mfg. Parker Airborne
0054	2C27-3	1BB27	Cartridge, Fuel Boost Pump, Cond. 7	7	1	Removed from a Bell 412 on 12/7/11. Leaks from drain boss or around positive lead post. Mfg. Parker Airborne
0055	LW-14445-11P	DEN8715	Valve Assy, Cond. 7	7	1	Removed from a Lycoming engine on 7/29/10. Core, TBO, requires overhaul. Mfg. Rayjay Consolidated Fuel Systems
0056	LW-14445-11P	EHN15126	Valve Assy, Cond. 7	7	1	Removed from a Lycoming engine on 10/6/11, requires overhaul. Mfg. Rayjay Consolidated Fuel Systems
0057	LW-18861	FGN00377	Bypass Valve, Cond. 7	7	1	Removed from a Cessna 206 on 1/16/14, internal/external oil leaks. Mfg. Kelly Aerospace
0058	3053995CL12	NSN	Trim Thermocouple, Cond. 7	7	1	Removed from a King Air B300C on 5/29/13. Yellow wire broken. Mfg. Hawker Beechcraft
0059	23053176	FF14794	Valve Assembly, Bleed Air, Cond. 7	7	1	Removed from an MD369 on 8/31/15, core, has Rolls Royce service accessory card dated 6/20/14. Overhaul and certify. Mfg. Rolls Royce
0060	S-3008EC-6	R3942	Compressor, Air Conditioning, Cond. 7	7	1	Removed from a Bell 407 on 11/25/15, throws engine oil. Mfg. Sanden
0061	069-1025-27	48777	Transceiver, NAV Comm, KX-165, Cond. 7	7	1	Removed from a Cessna 210 on 11/27/15. Display inop, won't dim. Mfg. Bendix King
0062	A-10055-B	149656	Pump, Fuel T206, Cond. 7	7	1	Removed from a Cessna 206 on 10/29/12, time change. Overhaul and certify. Mfg. Weldon
0063	2682001-1	N/A	Brake Master Cylinder, Cond. 7	7	2	Removed from a Cessna 208B on 10/8/13, unit check. Total time 677.2, Total cycles 570 Mfg. Cessna
0064	470954-9005	MC000141	Bypass Valve, Cond. 7	7	1	Removed from a Lycoming engine on 3/18/13, metal in oil. Mfg. Kelly Aerospace
0065	8061-330	2485459	Fuel Control Assembly, Cond. 7	7	1	Removed from a King Air B300C on 12/26/12, sloppy shaft. Mfg. Woodward
0066	C165004-0501	DE08912	Waste Gate Controller, Cond. 7	7	1	Removed from a Cessna 210 on 5/23/14, condition unknown. Mfg. Rayjay Consolidated Fuel Systems.
0067	7030	292680	Vertical Speed Indicator, Cond. 7	7	1	Removed from an Airbus AS350 on 12/8/15. Upgrade, removed in working condition. Mfg. United Instruments
0068	066-3044-01	3704	KN1 416 Radar Altimeter Indicator, Cond. 7	7	1	Removed from an Airbus AS350 on 12/8/15. Upgrade, removed in working condition. Mfg. Bendix King
0069	3839949002	6419	Airspeed Indicator, Cond. 7	7	1	Removed from an Airbus AS350 on 12/8/15. Upgrade, removed in working condition. Mfg. Badin-Crouzet
0070	066-1072-14	75603	Receiver, ADF, KR-87, Cond. 7	7	1	Removed from an Airbus AS350 on 12/7/15. Upgrade, removed in working condition. Mfg. Bendix King
0071	066-1068-04	30363	KN 62A DME, Cond. 7	7	1	Removed from an Airbus AS350 on 12/7/15. Upgrade, removed in working condition. Mfg. Bendix King
0072	071-1234-00	76458	KA 44B ADF Antenna, Cond. 7	7	1	Removed from an Airbus AS350 on 12/8/15. Upgrade, removed in working condition. Mfg. Bendix King.
0073	011-00147-00	60003522	Antenna, Cond. 7	7	1	Removed from a Airbus 350B2 on 12/8/15. Removed in working condition. Mfg. Garmin
0074	814-30077	102	NVIS Light Box, Cond. 7	7	1	Removed from a Airbus 350B2 on 12/8/15. Upgrade, removed in working condition. Mfg. Ahlers
0075	01-0770875-01	01651	Green LED Position Light, Cond. 7	7	1	Removed from an Airbus AS350 on 12/18/15. Upgrade, removed in working condition. Mfg. Whelen Engineering
0076	071-1242-06	32474	Accessory, Slaving, Ka51b, Black, Vertical Faceplate, Cond. 7	7	1	Removed from an Airbus AS350 on 12/8/15. Upgrade, removed in working condition. Mfg. Bendix King

Excess Justification Report

For Excess Lot

FY16-020

Item #	Part #	Serial #	Description	Cond	Qty	Remarks
0077	01-0770875-02	01017	Red LED Position Light, Cond. 7	7	1	Removed from an Airbus AS350 on 12/8/15. Upgrade, removed in working condition. Mfg. Whelen
0078	071-1052-00	62784	Transmitter, Flux Detector, Azimuth, Type Kmt, Cond. 7	7	1	Removed from an Airbus AS350 on 12/8/15. Upgrade, removed in working condition. Mfg. Bendix King
0079	1234T100-3TZ	2212-452	Gyro, Electric, Cond. 7	7	1	Removed from an Airbus AS350 on 12/8/15. Upgrade, removed in working condition. Mfg. Electric Gyro Corp.
0080	504-0111-920	504011191625061	Horizon Reference Indicator, Cond. 7	7	1	Removed from an Airbus AS350 on 12/8/15. Upgrade, removed in working condition. Mfg. L-3 Communications
0081	RS24-020	2326	Relay, Cond. 7	7	1	Removed from a Airbus 350B2 on 12/8/15. Upgrade, removed in working condition. Mfg. Northern Airborne Technology
0082	805-11500-001	JDP10002073	Processor, WX500 With Spacers 206, Cond. 7	7	1	Removed from a Cessna 206 on 5/4/16, condition unknown. Mfg. BF Goodrich
0083	23077068	AG21857	Nozzle Assembly, Fuel, Cond. 7	7	1	Removed from a Cessna 206 Soloy on 5/6/16. Total cycles: 3078, Total time: 4143.7 Overhaul and certify. Mfg. Rolls Royce
0084	066-3054-01	11424	Indicator, Cond. 7	7	1	Removed from a Cessna Soloy on 5/6/16. Has an repair tag from Soloy LLC, inop, no Alt. Indication. Mfg. Bendix King
0085	305952-00	307	Interface Adapter, Cond. 7	7	1	Has a repairable tag dated 4/28/16. ALTN TQ displayed on PFD. Mfg. Sandia Aerospace
0086	7G1147	286	Pressure Switch, Cond. 7	7	1	Removed from a Bell 412 on 5/18/11, intermittent. Mfg. Custom Control Sensors Inc.
0087	071-1052-00	74756	Transmitter, Flux Detector, Azimuth, Type Kmt, Cond. 7	7	1	Removed from a Bell 407 on 5/10/16. Has Helicopter Specialties Inc. component record card, doesn't allow for proper indication, always output 320-330 deg. nearing. Mfg. Bendix King
					89	